

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
NJ
7-CALDW,
5-

Cadmus House
159 Fairfield Avenue
West Caldwell
Essex County
New Jersey

HABS No. NJ-918

Photographer: David Hoffman

March 1985

Photographs are slight enlargements of 4"x5" negatives. See floor plan on data pages 36 and 37 for room identification. See site plan page 32 of data for location of fieldstone foundations at rear of property.

- NJ-918-1 VIEW NORTH, GENERAL VIEW OF FRONT ELEVATION AND SURROUNDING LOT
- NJ-918-2 VIEW NORTH, SOUTHEAST (FRONT) ELEVATION
- NJ-918-3 VIEW NORTHWEST, FRONT ELEVATION
- NJ-918-4 VIEW NORTHEAST, SOUTHWEST ELEVATION WITH EXPOSED END CHIMNEY BASE
- NJ-918-5 VIEW EAST, NORTHWEST AND SOUTHWEST ELEVATIONS
- NJ-918-6 VIEW SOUTHEAST, NORTHWEST (REAR) ELEVATION AND WELL
- NJ-918-7 VIEW SOUTH, REAR OF HOUSE AND GARAGE, GENERAL VIEW OF LOT
- NJ-918-8 VIEW SOUTHWEST, NORTHEAST ELEVATION
- NJ-918-9 FIRST FLOOR, FRONT HALL (ROOM B), SHOWING STAIRWAY IN NORTHEAST WING AND DOORS TO PARLOR (RIGHT) AND DINING ROOM (LEFT), LOOKING NORTHWEST
- NJ-918-10 FIRST FLOOR, ROOM B, FRONT DOOR, LOOKING SOUTHEAST
- NJ-918-11 FIRST FLOOR, PARLOR (ROOM C) LOOKING NORTHEAST, SHOWING BUILT-IN CUPBOARD AND FIREPLACE
- NJ-918-12 FIRST FLOOR, PARLOR (ROOM C) LOOKING SOUTHEAST, FRONT WINDOWS AND EXPOSED BEAMS
- NJ-918-13 FIRST FLOOR, PARLOR (ROOM C), LOOKING SOUTHWEST, DOOR TO FRONT HALL
- NJ-918-14 FIRST FLOOR, PARLOR (ROOM C), LOOKING NORTHWEST, DOOR TO NEW KITCHEN

(continued)

CADMUS HOUSE
HABS No. NJ-918 (Page 2)
Index to Photographs

- NJ-918-15 FIRST FLOOR, DINING ROOM (ROOM A), LOOKING SOUTH, FIREPLACE AND EXPOSED BEAMS
- NJ-918-16 FIRST FLOOR, DINING ROOM (ROOM A), LOOKING WEST, HEARTH AND WAINSCOTE
- NJ-918-17 FIRST FLOOR, DINING ROOM (ROOM A), LOOKING EAST, DOOR TO NEW KITCHEN AND ENCLOSED STAIR IN SOUTHWEST WING
- NJ-918-18 FIRST FLOOR, DINING ROOM (ROOM A), LOOKING NORTH, REAR DOOR, ENCLOSED STAIR IN SOUTHWEST WING, AND DOOR TO FRONT HALL
- NJ-918-19 FIRST FLOOR, KITCHEN (ROOM D), LOOKING NORTHEAST
- NJ-918-20 FIRST FLOOR, KITCHEN (ROOM D), LOOKING SOUTHWEST
- NJ-918-21 FIRST FLOOR, BATHROOM, LOOKING SOUTHWEST FROM UTILITY ROOM
- NJ-918-22 FIRST FLOOR, BATHROOM, LOOKING NORTHWEST
- NJ-918-23 FIRST FLOOR, BATHROOM, LOOKING NORTHEAST
- NJ-918-24 SECOND FLOOR, ROOM E, LOOKING NORTHEAST, STAIR FROM FIRST FLOOR
- NJ-918-25 SECOND FLOOR, ROOM E, LOOKING SOUTHEAST, EYEBROW WINDOWS ON FRONT WALL
- NJ-918-26 SECOND FLOOR, ROOM E, LOOKING SOUTHWEST, END WALL WINDOWS AND CHIMNEY
- NJ-918-27 SECOND FLOOR, HALL (ROOM F), LOOKING NORTHWEST
- NJ-918-28 SECOND FLOOR, HALL (ROOM F), LOOKING EAST, DOORS TO ROOMS G, H AND I
- NJ-918-29 SECOND FLOOR, ROOM I, LOOKING NORTHEAST
- NJ-918-30 SECOND FLOOR, ROOM I, LOOKING SOUTH INTO ROOM H AND HALL
- NJ-918-31 SECOND FLOOR, ROOM H, LOOKING EAST, EYEBROW WINDOWS
- NJ-918-32 SECOND FLOOR, ROOM H, LOOKING NORTHEAST, MANTEL

(continued)

CADMUS HOUSE
HABS No. NJ-918 (Page 3)
Index to Photographs

- NJ-918-33 SECOND FLOOR, ROOM H, LOOKING WEST
- NJ-918-34 SECOND FLOOR, ROOM G, LOOKING SOUTHEAST
- NJ-918-35 VIEW NORTHWEST, REMAINS OF DRY LAID FIELDSTONE FOUNDATION OF CARRIAGE SHED OR BARN
- NJ-918-36 VIEW SOUTHWEST, FOUNDATION REMAINS OF CIRCA 1920s COW BARN
- NJ-918-37 VIEW EAST, FOUNDATION REMAINS OF SILO ASSOCIATED WITH TWENTIETH CENTURY COW BARN
- NJ-918-38 VIEW NORTHWEST, FIELDSTONE SECTION OF FOUNDATION REMAINS OF TWENTIETH CENTURY COW BARN
- NJ-918-39 Photographic copy of photographs (originals in possession of Mary A. Vreeland), photographer not stated
- UPPER LEFT AND RIGHT: DINING ROOM AND PARLOR DECORATED FOR CHRISTMAS, CIRCA 1979
- LOWER LEFT: VIEW SOUTHEAST, REAR DOOR, CIRCA 1930s
- LOWER RIGHT: VIEW NORTHWEST, FRONT ELEVATION, CIRCA 1930s